

General Data

Change Nr, Title 20005758, AHF VIEWER V03.01.01.05 to V03.01.01.06
Date of issue 13.09.2019

Category of change

- ☐ Materials
- ☐ Method
- ☐ Manufacturing place
- ☐ Machine
- ☐ Form
- ☐ Fit
- ☒ Function

Affected products

All ecosine active products. The AHF Viewer 2 Software is a PC tool (program) used to connect PC to ecosine active devices for tuning, monitoring and troubleshooting.

Description of change

Update AHF Viewer 2 software to version V03.01.01.06.

Reason for change

- Reason 1: AHF Viewer 2 SW from version V03.01.01.05 to V03.01.01.06
Reason 2: Bug fixes improving handling of EventLogs.

Impact for the customer**1. New Features**

None

2. Bug Fixes**Improved Eventlog download**

- Disabling the download Eventlog buttons during downloading
- Improving stability when downloading Eventlog from device

Added new default parameter file

Replacing the default parameter file with the current one from Power Module firmware V03.02.05

Identification

Check "Help > About AHF Viewer ecosine active sync" in the menu of the main window.

Estimated Schedule

New SW version improves download of eventlog. Previous still can be used. In general, upgrading to new version is recommended but not mandatory.

Customer enquiries

You may address any technical enquiries regarding this PCN by sending an E-Mail to pcn@schaffner.com. Please refer to the "Change number" on page 1 for faster response.

Quality assurance measures

Application of ISO9001:2015 and exceeding Schaffner standards for outstanding quality in all involved design centers and manufacturing locations.

Date of announcement

23.09.2019

Schaffner Group
Nordstrasse 11
CH-4542 Luterbach
www.schaffner.com

Appendix

List of affected products

Schaffner Mat. Nr.	Schaffner Description	Customer Mat. Nr.
817650	SYNC300A	
820789	SYNC300X	
820791	SYNC300S	
817645	FN3540	
817646	FN3541	
819435	FN3530	
819436	FN3531	
819437	FN3532	
819438	FN3542	
820792	FS3530	
820793	FS3540	
817501	FN3545-X0603WXXP	
817502	FN3545-X0603WLXP	
817507	FN3545-X0604WXXP	
817508	FN3545-X0604WLXP	
817513	FN3545-X1203WXXP	
817514	FN3545-X1203WLXP	
817519	FN3545-X1204WXXP	
817520	FN3545-X1204WLXP	
817525	FN3545-X1803WXXP	
817526	FN3545-X1803WLXP	
817531	FN3545-X1804WXXP	
817532	FN3545-X1804WLXP	
817537	FN3545-X2403WXXP	
817538	FN3545-X2403WLXP	
817543	FN3545-X2404WXXP	
817544	FN3545-X2404WLXP	
817549	FN3545-X3003WXXP	
817550	FN3545-X3003WLXP	
817555	FN3545-X3004WXXP	
817556	FN3545-X3004WLXP	
820514	FN3545-S0603WXXP	
820515	FN3545-S0603WLXP	
820516	FN3545-S0604WXXP	
820517	FN3545-S0604WLXP	
820518	FN3545-S1203WXXP	
820519	FN3545-S1203WLXP	
820520	FN3545-S1204WXXP	
820521	FN3545-S1204WLXP	
820522	FN3545-S1803WXXP	
820523	FN3545-S1803WLXP	
820524	FN3545-S1804WXXP	
820525	FN3545-S1804WLXP	
820526	FN3545-S2403WXXP	
820527	FN3545-S2403WLXP	
820528	FN3545-S2404WXXP	
820529	FN3545-S2404WLXP	
820530	FN3545-S3003WXXP	
820531	FN3545-S3003WLXP	
820532	FN3545-S3004WXXP	
820533	FN3545-S3004WLXP	

The listed material numbers are being modified. Related materials that are not explicitly listed on this PCN are not being modified nor discontinued as per the PCN. All mentioned dates apply only to materials explicitly listed on this PCN.