

General Data

Change Nr, Title 20009207, Update bom for 800571 tox process
Date of issue 24.02.2023

Category of change

- ☒ **Form**
- ☐ **Fit**
- ☐ **Function**
- ☐ **Men**
- ☒ **Material**
- ☐ **Method**
- ☐ **Machine**

Affected products

800571 FN530-16-99

Description of change

The housing assembly process was changed from tox clinching to riveting.

Reason for change

Better connection


Impact for the customer

No impact on specifications nor performance.

Identification

Rivets are visible in the housing sheet metal.

Estimated Schedule



Expected date of first manufacturing acc. new design:

production site	encoded date	production date code
China	2023CW09	2309

Dependent on depletion of current inventory of material, customer may continue to receive current material beyond the planned "first manufacturing new design".

Customer enquiries

You may address any technical enquiries regarding this PCN by sending an E-Mail to pcn@schaffner.com. Please refer to the "Change number" on page 1 for faster response.

Quality assurance measures

Application of ISO9001:2015 and exceeding Schaffner standards for outstanding quality in all involved design centers and manufacturing locations.

Others

Date of announcement

28.02.2023

Schaffner Group
 Nordstrasse 11e
 CH-4542 Luterbach
www.schaffner.com